

# GRAM

**SERIES** 

C<sub>6</sub>P

Indicator / Printer



EN







INDEX	English
Safety guide	3
Technical performance	3
Operation	5
Power on	5
Time	5
Date	5
Number operation	5
Statistics Printing	6
General Printing	6
Auto Printing	7
Division Value	7
Backlight	7
Accumulation	7
Accumulation check	8
Pre-set Tare	8
Parameters setting	8
Zero and baud rate setup	8
Printing parameters setup	9
Collecting printing	9
Setting up channel	10
Off time setting	10
Calibration	11

Guarantee \_\_\_\_\_\_12



# **ENGLISH**

### **SAFETY GUIDE**

Read carefully the following instruction and advice before using this scale.

- Over-loading this scale is harshly prohibited
- Refrain from long-time loading that could lead to excessive fatigue on loadcell used inside the scale. Excessive fatigue on loadcell would decrease the accuracy and shorten the life of scale.
- Check the shackle and hook regularly.
- Check the battery power level before/after use and recharge the scale in time.
- In order to maximize the battery life, periodic recharging is necessary for scales even not in use for long time.
- Do not try to repair the scale by yourselves.
- Use privately attached charger only.
- The scale can show the cell capacity when power on. For example when U
  86 is shown, meaning the current cell capacity is 86%. If the cell capacity
  is 20%, please charge the scale as soon as possible to avoid damaging
  the battery.

### **TECHNICAL PERFORMANCE**

1. Accuracy: Level III

2. Internal resolving power: 1/60 ten thousand



# 3. Technical performance of sensor:


Non linear – return error: ±0.02%R.0 Light change: ±0.025%R.0/20 minute

Sensitive: 2.02±0.004mV/V Supply voltage: 3.7V DC

4. Voltage: 7.4V DC

5. **Power:** Approximate 0.2W

- 6. **Operation temperature:** weighing display unit between 0°C to 40°C, sensor -20°C +40°C r
- 7. Relative humidity: 10 90% RH
- 8. Distance between weighing display unit and scale is no greater than 150 meters.





### **OPERATION**

### Power on

Please turn on the crane scale first and then turn on the indicator pressing the  $\overbrace{\ \ \ \ \ }$  key.

### Time

In weighing status, if check time, press key  $\binom{6}{4}$ , it displays current time like 12:23:20.

Time adjustment: Press key F, input "16" then press E, it displays time like "122320", input the correct time like "122530" then press E. The time has been adjusted.

# Date

In weighing status, if check date, press key 7/10, it displays current date like 11.03.10.

**Date adjustment:** Press key (F), input "17" then press (E), it displays date like "110310", input the correct date like "110315" then press (E). The date has been adjusted.

# Number operation

If checking number of current goods, press key  $\frac{9}{NO}$ , it displays goods No. at lower left corner.

**Modify Number:** Press (F), input "19" then press (F), it displays original No., input the number you want then press (F) to modify.

5



# **Statistics Printing**

If a batch of goods need to be weighed for several times, it needs this printing mode. Press key , it is statistics printing. It prints out No. of the goods, date, serial number, time and weight.

For example, if first time the weight is 1000kg, press ( ), it'll print serial number "0001", time "12:30:30", weight "1000". Then press ( ) every time after weighing the goods, after finishing weighing all the goods, press key ( ) accumulate all the weights and print out then quit the mode.


### Sample

WEIGHT MEMO	
****	
Ser No. (kg)	No.: 0000 Date: 11/04/30 Time Weight
0001 0002 0003	13:24:53 1000 13:25:24 2000 13:25:39 1000

# **General Printing**

When weighing goods, after the stable light on, press key ( ), it'll print out No. of the goods, date, time, tare weight, gross weight, net weight.

Sample






### **Auto Printing**

This indicator has auto printing function, press key (AUTO), it will print out like statistics printing mode. It'll print automatically every time after stable light on. After finishing weighing, press (AUTO) again, it'll accumulate and quit the mode.

### Sample



### **Division Value**

If modify division value, press  $\frac{8}{e}$  it displays "P 0" means no decimal point of division value, e.g.: to set division 0.5kg, input 1 (P 1) then press it displays "d 1", input 5 (d 5) then press  $\boxed{\leftarrow}$ . Finished now the division value is 0.5kg.

### **Backlight**

Press key  $(\mbox{$\frac{1}{3}$})$  to turn on / off the backlight.

# Accumulation

 $\mathsf{Key} \stackrel{\mathsf{Accu}}{}{}$  is used in statistics printing mode, to accumulate the weights and quit the mode.



### **Accumulation check**

In statistics printing mode, press  $\ensuremath{\text{\tiny CCH}}\xspace$  and check the total weights.

### **Pre-set Tare**

Press key  $\frac{5}{100}$ , it displays **[p 0]**, input tare value like 879kg, then press  $\boxed{\Box}$ .

### **PARAMETERS SETTING**

### Zero and baud rate setup

- 1. Press (F) to enter into parameters setting and input "18", then press (E).
- 2. The display will show (F1 1): Zero function range setup, choose "0 means 0%", "1 means 2%", "2 means 20%", "3 means 50%", "4 means 100%". Select the desired option and press ( to confirm and go to next parameter.
- 3. **The display will show (F2 2):** Zero function range of power on, choose "0 means 0%", "1 means 4%", "2 means 50%", "3 means 100%". Select the desired option and press ( to confirm and go to next parameter.
- 4. **The display will show (F3 05):** Zero-tracking range, choose "5 means 0.5e", "10 means 1e", max is "20 means 2e", then press to confirm and go to next parameter.
- 5. **The display will show (F4 4):** Baud rate of wireless, choose "1 means 600bps", "2 means 1200bps", "3 means 4800bps", "4 means 9600bps", then press ( to confirm and go to next parameter.
- 6. **The display will show (F5 4):** Baud rate of RS232, choose "1 means 600bps", "2 means 1200bps", "3 means 4800bps", "4 means 9600bps", then press ( to confirm.



7. The display will show "**END**" press  $(\subseteq)$  to back to normal weighing mode.

# Printing parameters setup



- 2. **The display will show (p1 0):** Setup print out whether back to "0" or not, choose "0" means back to 0 and print, "1" for not back to 0 and print, then press ( to confirm and go to next parameter.
- 3. **The display will show (p2 1):** Setup pieces of printing bill, choose "1 means 1pc", "2 means 2pcs", "3 means 3pcs", then press confirm and go to next parameter.
- 4. The display will show (P3 0): Setup time of auto printing after stable light on, choose "0 means the time after stable", "1 means 1s after stable", "2 means 2s" and the longs time is 3s, press ( ).
- 5. The display will show **"END"** press ( ) to back to normal weighing mode.

### **Collecting printing**

- 1. Press (F) key, input "15" and press (E), it displays "pt 0".
- 2. Input "1" it displays "pt 1": Means print out all weights which under the same No. of goods. Press ( to confirm, it displays "0" meaning input No. of the goods like "1234" and press ( It displays "pn 0", 0 means simple mode which only print out the total weight of the goods No.; 1 means print the details of the goods No., input the value and press ( it'll begin printing.
- 3. Input "2" it displays "pt 2": Means print out all weights which use same



date. Press and input the date you want like 110304, and press it displays "pn 0", 0 means simple mode which only print out the total weight of the goods No.; 1 means details, input the value and press it'll begin printing.

- 4. Input "3" it displays "pt 3": Means print out all the data. Press ( ) and it displays "pn 0", 0 means simple mode which only print out the total weight of the goods No.; 1 means details, input the value and press it'll begin printing.
- 5. **Delete data:** Press F and input "72851", press E then all the data will be deleted.

# Setting up channel

- 1. Press (F) key, it displays "**P 00**", Input[20] and press (E).
- 2. The display will show "pd 01". 01 means the channel number, input the channel number you want directly by digital key and press key (E), it shows "END", then press (E) again to confirm and finish.

### Off time setting

- 1. Press F key, it displays "P 00", Input[30] and press E.
- 2. The display will show "dl 01", 01 means half an hour to power off; 02 means an hour; 03 means one and a half hour) press it show "END", then press ( to confirm and finish.



### **CALIBRATION**

- 1. Press (F), input password "13386" and press (E).
- 2. It displays "**d** \*", \* means division value, you can choose 1, 2, 5, 10, 20, 50 and then press  $\bigcirc$
- 3. It displays "P \*", \* means decimal points of division value, choose 0 for no decimal or 1 means 1 decimal; then press ( ).
- 4. It displays Max capacity like **"05000"**, input Max Cap you want and press
- 5. It displays "**noload**", wait until stable light on and press  $\bigcirc$
- 6. It displays **F.S.**, load weights onto the scale (like 3000kg), input value of weights like **"03000"**, wait until the stable light on, then press ( ).
- 7. Finished.



### **GUARANTEE**

This scale is guaranteed for one year from the delivery date. The guarantee covers any fabrication defect of the material.

During this period **GRAM PRECISION, SL,** covers the manpower and the spare parts necessary for the reparation of the scale.

This guarantee does not cover the failures caused by an inappropriate use or overcharge.

The guarantee does not cover the freight cost (transport) necessary to repair the scale.



# **NOTAS**



### Gram Precision S.L.

Travesía Industrial,  $11\cdot 08907$  Hospitalet de Llobregat · Barcelona (Spain) Tel. +34 902 208 000 · +34 93 300 33 32 Fax +34 93 300 66 98 comercial@gram.es www.gram-group.com